

Terminal releasing documentation


WEB-CON-000606

Supplier Tyco/ 1534171-1


Articleno. 1J0 972 930 A

Replaced —

Secondary



Detail Secondary locking



Secondary lock: 1




Primary lock: 1

Colour: black

Mating

connector: -

Tool WEB-ENT-30-0002-98



In this documentation, you will see application examples. These examples may differ in colour and number of pins. TKR cannot provide repair manuals. In dieser Dokumentation werden Anwendungsbeispiele gezeigt. Diese Beispiele können sich in Farbe und Poligkeit unterscheiden. TKR kann keine Reparaturanleitung vorgeben.

Pins 10

Type


female

Mating conn. —

Seal

no

Primary




Repair wire WEB-REP-000...

...010, ...011, ... 139



Measuring lead WEB-MES-000...

...083



Tool WEB-ENT-12-0046-98

